

Re-sampling/ Remediation - Lead In Water at Vestal School District (2023)

| VCSD Building | Sample Location | Source Type | Floor | Baseline Testing Date | Delta Sample ID# | Baseline Lab Results (ug/L) | Immediate Action | Re-sampling Testing Date | Delta Sample ID# | Re-sampling Lab Result (ug/L) | Remediation |
|-------------------------------|-----------------------------|---------------------|-------|-----------------------|------------------|-----------------------------|------------------|--------------------------|------------------|-------------------------------|---|
| African Road Elementary (ARE) | Room 156 Coaches office | Sink | 1 | 5/20/2023 | ARE2023-28 | 10.4 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| African Road Elementary (ARE) | Kitchen | Mixing Valve Faucet | 1 | 5/20/2023 | ARE2023-40 | 12.1 | Disable | | | | |
| African Road Elementary (ARE) | Kitchen | Sink | 1 | 5/20/2023 | ARE2023-41 | 19.2 | Signage | | | | |
| Central Jr. / Cub Care (CJR) | Kitchen, Room 212 | Sink | 2 | 5/18/2023 | CJR2023-4 | 27.3 | Signage | | | | |
| Central Jr. / Cub Care (CJR) | Bathroom 103 | Sink | 1 | 5/18/2023 | CJR2023-19 | 11.2 | Signage | | | | Not a source of potable water. Warning signs installed. |
| Central Jr. / Cub Care (CJR) | Room 109 Bathroom | Sink | 1 | 5/18/2023 | CJR2023-26 | 998 | Disable | N/A | N/A | N/A | Taken out of service. |
| Central Jr. / Cub Care (CJR) | Room 109 Bathroom | Sink | 1 | 5/18/2023 | CJR2023-27 | 1060 | Disable | N/A | N/A | N/A | Taken out of service. |
| Central Jr. / Cub Care (CJR) | 1st Floor East Hallway | Fountain | 1 | 5/18/2023 | CJR2023-30 | 7.7 | Signage | | | | |
| Central Jr. / Cub Care (CJR) | East Mens Bathroom | Sink | 1 | 5/18/2023 | CJR2023-31 | 11.2 | Signage | N/A | | | Not a source of potable water. Warning signs installed. |
| Clayton Ave Elementary (CAE) | Room 122, Art | Sink | 1 | 5/18/2023 | CLA2023-3 | 9.7 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Clayton Ave Elementary (CAE) | Gym Office | Sink | 1 | 5/18/2023 | CLA2023-6 | 10.5 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Clayton Ave Elementary (CAE) | Upper Cafeteria | Warming Hose | 1 | 5/18/2023 | CLA2023-13 | 49.7 | Signage | | | | |
| Clayton Ave Elementary (CAE) | Coaches Office | Sink | B | 5/18/2023 | CLA2023-21 | 7.8 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Clayton Ave Elementary (CAE) | Classroom 103 | Fountain | 1 | 5/18/2023 | CLA2023-35 | 8.7 | Disable | | | | |
| Clayton Ave Elementary (CAE) | Classroom 104 | Fountain | 1 | 5/18/2023 | CLA2023-38 | 61.3 | Disable | | | | |
| Clayton Ave Elementary (CAE) | Classroom 105, Bathroom | Sink | 1 | 5/18/2023 | CLA2023-38 | 11.5 | Signage | | | | |
| Clayton Ave Elementary (CAE) | Classroom 109 | Fountain | 1 | 5/18/2023 | CLA2023-43 | 56.6 | Disable | | | | |
| Clayton Ave Elementary (CAE) | Classroom 109 | Sink | 1 | 5/18/2023 | CLA2023-54 | 5.7 | Signage | | | | |
| Clayton Ave Elementary (CAE) | Classroom 201 | Sink | 2 | 5/18/2023 | CLA2023-68 | 11.2 | Signage | | | | |
| Clayton Ave Elementary (CAE) | Classroom 213 | Sink | 1 | 5/18/2023 | CLA2023-95 | 19.0 | Signage | | | | |
| Clayton Ave Elementary (CAE) | Ext. Playground Out Bldg | Hose Bib 1 [L] | Ext | 5/18/2023 | CLA2023-101 | 22.6 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Glenwood Elementary (GLE) | Kitchen | Sink | 1 | 5/19/2023 | GLE2023-6 | 6.6 | Signage | | | | |
| Glenwood Elementary (GLE) | Main Office | Sink | 1 | 5/19/2023 | GLE2023-7 | 6.3 | Signage | | | | |
| Glenwood Elementary (GLE) | Library | Sink | 1 | 5/19/2023 | GLE2023-49 | 16.0 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Glenwood Elementary (GLE) | Classroom 141 | Fountain | 1 | 5/19/2023 | GLE2023-65 | 10.4 | Disable | | | | |
| Tioga Hills Elementary (VHE) | Boiler Room | Sink 1 | B | 5/16/2023 | THE2023-1 | 15.3 | Signage | | | | Not a source of potable water. Warning signs installed. |
| Tioga Hills Elementary (VHE) | Cafetorium | Sink 3 | 1 | 5/16/2023 | THE2023-4 | 7.2 | Signage | | | | |
| Tioga Hills Elementary (VHE) | Girl's Locker Room | Sink 2 | 1 | 5/16/2023 | THE2023-15 | 6.6 | Signage | | | | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Room 279, Teacher's Counter | Sink | 2 | 5/23/2023 | VHS2023-25 | 9.0 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Room 277 | Sink 5 | 2 | 5/23/2023 | VHS2023-31 | 20.7 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Room 278, Boy's Bathroom | Sink 3 | 2 | 5/23/2023 | VHS2023-35 | 12.0 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Room 278A, Girl's Bathroom | Sink 3 | 2 | 5/23/2023 | VHS2023-38 | 6.1 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Room 274 Teacher's Counter | Sink 1 | 2 | 5/23/2023 | VHS2023-39 | 14.2 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Room 274 | Sink 2 | 2 | 5/23/2023 | VHS2023-40 | 62.3 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Room 274 | Sink 3 | 2 | 5/23/2023 | VHS2023-41 | 11.1 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Room 274 | Sink 4 | 2 | 5/23/2023 | VHS2023-42 | 20.1 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Room 274 | Sink 5 | 2 | 5/23/2023 | VHS2023-43 | 10.9 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Room 274 | Sink 6 | 2 | 5/23/2023 | VHS2023-33 | 14.6 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Room 274A/272A | Sink | 2 | 5/23/2023 | VHS2023-35 | 10.6 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Room 272 Teacher's Counter | Sink 1 | 2 | 5/23/2023 | VHS2023-49 | 13.4 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Room 272 | Sink 3 | 2 | 5/23/2023 | VHS2023-51 | 15.1 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |

| | | | | | | | | | | | |
|--------------------------|-----------------------------|------------------|---|-----------|-------------|--------|---------|-----|-----|-----|---|
| Vestal High School (VHS) | Room 272 | Sink 4 | 2 | 5/23/2023 | VHS2023-52 | 16.6 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Room 272 | Sink 5 | 2 | 5/23/2023 | VHS2023-53 | 5.1 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Room 265, Teacher's Counter | Sink 1 | 2 | 5/23/2023 | VHS2023-71 | 64.0 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Room 265 | Sink 6 | 2 | 5/23/2023 | VHS2023-76 | 70.7 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Room 265 | LHS | 2 | 5/23/2023 | VHS2023-77 | 35.6 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Room 264 Teacher's Counter | Sink 1 | 2 | 5/23/2023 | VHS2023-78 | 9.9 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Room 264 | Sink 3 | 2 | 5/23/2023 | VHS2023-80 | 7.1 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Room 264 | LHS | 2 | 5/23/2023 | VHS2023-84 | 1020.0 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Room 263 | Sink 1 | 2 | 5/23/2023 | VHS2023-86 | 96.5 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Room 263 | Sink 3 | 2 | 5/23/2023 | VHS2023-89 | 53.0 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Room 263 | LHS | 2 | 5/23/2023 | VHS2023-93 | 32.6 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Room 262 | Sink 11 | 2 | 5/23/2023 | VHS2023-110 | 7.7 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Room 262 | LHS | 2 | 5/23/2023 | VHS2023-111 | 28.3 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Room 262A | LHS | 2 | 5/23/2023 | VHS2023-113 | 23.8 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Room 261 | Sink 1 | 2 | 5/23/2023 | VHS2023-114 | 45.5 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Room 261 | Sink 2 | 2 | 5/23/2023 | VHS2023-115 | 7.4 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Room 261 | LHS | 2 | 5/23/2023 | VHS2023-120 | 64.1 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Room 260 Lecture Hall | Sink | 2 | 5/23/2023 | VHS2023-121 | 7.7 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Room 258 | Sink 1 | 2 | 5/23/2023 | VHS2023-122 | 72.6 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Room 258 | LHS | 2 | 5/23/2023 | VHS2023-133 | 33.1 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Room 256 | Sink 4 | 2 | 5/23/2023 | VHS2023-139 | 7.5 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Room 256 | Sink 5 | 2 | 5/23/2023 | VHS2023-140 | 10.0 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Room 256 | Sink 6 | 2 | 5/23/2023 | VHS2023-141 | 40.8 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Room 256 | Sink 8 | 2 | 5/23/2023 | VHS2023-143 | 33.4 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Room 256 | Sink 9 | 2 | 5/23/2023 | VHS2023-144 | 27.0 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Room 256 | Sink 10 | 2 | 5/23/2023 | VHS2023-145 | 20.9 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Room 256 | LHS | 2 | 5/23/2023 | VHS2023-147 | 5.2 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Room 242B, Girls Bathroom | Sink 1 | 2 | 5/23/2023 | VHS2023-148 | 9.1 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Room 242A, Boy's Bathroom | Sink 3 | 2 | 5/23/2023 | VHS2023-153 | 53.0 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Room 158, Library Office 1 | Sink | 1 | 5/23/2023 | VHS2023-175 | 46.1 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Room 136B, Girls Bathroom | Sink 3 | 1 | 5/23/2023 | VHS2023-184 | 16.7 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Room 135A, Girls Bathroom | Sink 1 | 1 | 5/23/2023 | VHS2023-194 | 32.9 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Kitchen, Room 101.2 | Sink 3 | 1 | 5/23/2023 | VHS2023-203 | 6.4 | Signage | | | | |
| Vestal High School (VHS) | Kitchen, Room 101.2 | Sink 4 | 1 | 5/23/2023 | VHS2023-204 | 30.8 | Signage | | | | |
| Vestal High School (VHS) | Room 100, Nurse Recovery | Sink 1 | 1 | 5/23/2023 | VHS2023-216 | 17.5 | Signage | | | | |
| Vestal High School (VHS) | Room 100.3, Recovery 2 | Sink | 1 | 5/23/2023 | VHS2023-218 | 36.2 | Signage | | | | |
| Vestal High School (VHS) | Room A25, Bathroom | Sink | B | 5/23/2023 | VHS2023-259 | 13.5 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Room B46 | Sink 1 | B | 5/23/2023 | VHS2023-272 | 5.5 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Room B42 | Sink 1, Faucet 2 | B | 5/23/2023 | VHS2023-278 | 20.4 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Room B42 | Sink 1, Faucet 2 | B | 5/23/2023 | VHS2023-280 | 25.4 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Room B40 | Sink 2 | B | 5/23/2023 | VHS2023-282 | 6.3 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal High School (VHS) | Room B48, Dark Room | Sink | B | 5/23/2023 | VHS2023-294 | 20.6 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |

| | | | | | | | | | | | |
|-------------------------------|---------------|------|---|-----------|------------|------|---------|-----|-----|-----|---|
| Vestal Hills Elementary (VHE) | Room 204 (PE) | Sink | 2 | 5/17/2023 | VHE2023-33 | 20.7 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
|-------------------------------|---------------|------|---|-----------|------------|------|---------|-----|-----|-----|---|

| | | | | | | | | | | | |
|----------------------------|--------------------------|--------|---|-----------|------------|-----|---------|-----|-----|-----|---|
| Vestal Middle School (VMS) | Boys Bathroom (2) by 213 | Sink 3 | 2 | 5/20/2023 | VMS2023-22 | 6.7 | Signage | | | | Not a source of potable water. Warning signs installed. |
| Vestal Middle School (VMS) | Room 139 | Sink | 1 | 5/20/2023 | VMS2023-53 | 7.9 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal Middle School (VMS) | Room 110 | Sink | 1 | 5/20/2023 | VMS2023-65 | 5.7 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |
| Vestal Middle School (VMS) | Room 127 | Sink 3 | 1 | 5/20/2023 | VMS2023-90 | 8.4 | Signage | N/A | N/A | N/A | Not a source of potable water. Warning signs installed. |

Highlighted fixtures retested below 5.0 ppb following remediation.

Highlighted fixtures final results over 5 PPB & have been taken out of service and are no longer in use.

Highlighted fixtures final results over 5 PPB and are not used for drinking water. Warning signs installed.